

**WO #:** PE52042

**WO Desc:** M1 leak at west flange on M1 filter

**Parent WO#:**

**WO Long Desc:**

**WO Priority:** 1

**Location:** 28064

O- FHR RESEARCH & DEVELOPMENT LAB-PERU

**Asset:**

**Asset Service:**

**Entry Date:** 4/2/2014

**WO Status:** CLOSE

**Action Code:** LDAR

**Project #:**

**Originator:** SHERRY SCHAEFER

**Status Date:** 9/30/2014

**Work Type:** CM

**Failure Class:**

**Job Plan:**

**Planned Start:**

**Actual Start:** 4/2/2014

**Review Date:**

**PM/Bundle:**

**Planned Completion:**

**Actual Completion:** 4/2/2014

### Plant Information

**RC:** PERC02

**Planner:** WILLIAM STONEKING

**MOC#:**

**When Code:** RT

**Lead Craft:** MECH

**MOC Status:**

**P&ID:**

**MOC Desc:**

**SIR/EIS Required:**

### LDAR

**Tag #:**

**1st Attempt Made:**

**LDAR Planning Notes:**

**Leak Type:**

**1st Attempt Was:**

**LDAR Additional Notes:**

**Size:**

**1st Attempt Due By:** 4/7/2014

**Leak Location:**

**After 1st Attempt PPM:**

**Location Orientation:**

**Final Due By:** 4/17/2014

### Work Order Notes

JOSEPH VITTONI

04/02/2014 Replaced reducer and flange.

**Completed by Emp #:** \_\_\_\_\_

**Signature:** \_\_\_\_\_